



FALLING OBJECTS – MAINTENANCE AND WORKING AT HEIGHT

APRIL 28 **steelSafetyDay**




ACCESS TO AREAS BELOW OVERHEAD WORK must always **BE RESTRICTED**





Tools and materials should **never be stored overhead**



Helmets and safety glasses must be secured with a **strap or lanyard**



Material must never be thrown to the ground. **Purpose-built chutes must be used**

Temporary access platforms and scaffolding should be built with **toeboards and solid boards without gaps**

If something falls, work should **stop immediately** and a **full investigation** should be carried out with **corrective measures implemented before work recommences**